



Mereen-Johnson LLC

Service Bulletin #GRS-2-04/06
Machine Type - Gang Rip Saw
Subject - Feed Bed



Keeping your feed bed in proper operating condition can assure your machine's capability to provide a glue line finish and proper accuracy tolerances. The purpose of this service bulletin is to inform Mereen-Johnson Gang Rip Saw users of common service issues associated with the feed bed system.

For further information, contact your Mereen-Johnson Customer Service representative at 1-888-4MJ-SAWS (465-7297). Additional information is available in your operations manual. If you do not have an operations manual for your machine, contact your Customer Service representative to order a replacement.

Mereen-Johnson LLC
575 Ninth Street SE, Suite 200
Minneapolis, Minnesota 55414
USA

Phone (612) 529-7791 Fax (612) 529-0120

